

Southport owners,

The fountain in Pond 1 has been temporarily turned off. The main nozzle was spraying at its normal height, but the side nozzles were only reaching about one foot. This imbalance indicates a likely clog in the system. When this occurs, the fountain is automatically shut down to prevent damage to the pump.

A service call has been placed with Lake Doctors, and we are currently waiting for their scheduled visit. We hope to have the fountain back in operation soon.

Southport on the Bay Board of Directors.

January 2, 2026